| ECS Configuration Change Request | | | | Page 1 of 1 Page(s) | | | | |
|--|---|-----------|---|---|----------------------------|--|-----------------|--|
| 1. Originator | 2. Log Date: | 3. CCR #: | | 4. Rev: | 5. Tel: | 6. Rm # | 7. Dept. | |
| Byron V. Peters | 16 MAY00 | 00-0 | 54 4 | - | 301/883-4077 | 2101C | SED | |
| 8. CCR Title: Baseline Microcode Upgrades for STK Systems | | | | | | | | |
| 9. Qriginator Signature/Date | | | 10. C | lass | 11. Type: 12. Need Date: | | | |
| Dym V Files 5/16/00 | | | TT CCR | | | 5/20/00 | | |
| 13. Office Manager Signature/Date P. New geodoos 0516/00 | | | 14. Category of Change: Update ECS Baseline Doc. | | | 15. Priority: (If "Emergency" fill in Block 28). Routine | | |
| 16. Documentation/Drawings Impacted: | | | 7. Schedule 18. Cl(s) Affected:STMGT | | | aT . | | |
| 910-TDA-003 | | | | Impact: | | | | |
| 19. Release Affected by this Change: 20. Date due 1 | | | | stomer: 21. Estimated Cost: None - Under 100K | | | | |
| 22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other: | | | | | | | | |
| 23. Problem: (use additional Sheets if necessary) Errors on several STK systems have occurred recently that would be obviated with the release of newer microcode within the system. The vendor also requests that these changes be made in order to better support ECS. | | | | | | | | |
| Each of these microcode revisions have been tested at Landover. | | | | | | | | |
| 24. Proposed Solution: (use additional sheets if necessary) Upgrade STK 9840 to 1.25.114., Wolfcreek to 1.6.02, SD-3 to CTU 7.0, LMU to 1.9.04 and LCU to 3.8.04. Release notes attached. Note that the work of implementing this is up to STK. Sites should coordinate with STK as soon as possible to get this work | | | | | | | | |
| accomplished. | | | | | | | | |
| 25. Alternate Solution: (use additional sheets if necessary) | | | | | | | | |
| 26. Consequences if Change(s) are not approved: (use additional sheets if necessary) | | | | | | | | |
| | | | | | | | | |
| 27. Justification for Emergency (If Block 15 is "Emergency"): | | | | | | | | |
| 28. Site(s) Affected: ☐E | DF ☐PVC ☐VATC ☐ OC ☐ IDG Test Cell ☐ | EDC [|] GSFC | ∐LaRC | C □NSIDC □ |]SMC □AK | ∐JPL | |
| 29. Board Comments: 30. Work Assigned To: 31. CCR Closed Date: | | | | | | | | |
| 32. EDF/SCDV CCB Chair (| Sign/Date): Disp | | oproved | App/Co | m. Disapproved | Withdraw | Fwd/ESDIS ERB | |
| 33. M&O CCB Chair (Sign/l | | position: | | App/Co | m. Disapproved | 1 Withdraw i | wd/ESDIS ERB | |
| 34. ECS CCB Chair (Sign/D | eate): Dispo | 00 | | App/Cor | n. Disapproved | Withdraw | Fwd/ESDIS ERB | |
| | | _ | | | THE PERSON NAMED IN COLUMN | | ·· - | |

ORIGINAL

CM01JA00